



BMW GROUP AUSTRALIA. TAKATA AIRBAG RECALL AND REPLACEMENT TIMETABLE.

Type of airbag inflator	Time by which recall action must be initiated	Time by which inflators of this type must be replaced
Alpha Inflators	Within one week of commencement of this Recall Notice.	Within five business days after the replacement part arrives at the dealership nominated by the Consumer (or other such date as requested by the Consumer), where the replacement part is to be provided to the nominated dealership within two weeks of the Consumer request.
All other Affected Takata Airbag Inflators	As soon as practicable after the ACCC notifies a Supplier of approval or prescription of a Supplier's Communication and Engagement Plan under section 7(4) of this Recall Notice and on a rolling basis to allow for completion of replacement by the required dates.	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of this Schedule and the applicable Quarterly Completion Schedule.